
REAR VIEW
IMPORTANT: INPUT MUST BE WIRED TO BATTERY SIDE
OUTPUT
INPUT
-
HEAVY DUTY LOADS
+
REMOTE KEY SWITCH
OFF
ON
OUTPUT
INPUT
LED
+
-
RED
GREEN
BLACK
ON/OFF SWITCH
THESE TWO CABLES MUST BE TERMINATED INTO WAGO PLUG
+
-
BATTERY
IT IS IMPERATIVE THAT THE NEGATIVE (BLACK) FOR THIS UNIT IS TAKEN FROM THE SAME BATTERY THAT THE MD IS ISOLATING. FAILURE TO DO THIS WILL CAUSE THE UNIT TO WORK ERRATICALLY. ONLY ONE NEGATIVE MUST BE SUPPLIED TO EACH UNIT FOR CORRECT OPERATION.